

Service Information

PDD Contact : Reginald Thomas	Test or Evaluation : Test	Report Number : 52426
Received Date : 4/29/2014	Processed Date : 5/8/2014	Ground

Customer Information

Acct : ULINE
12575 ULINE DR
PLEASANT PRAIRIE, WI 53158

Contact: STEVE PLATEK

Phone: 2626124200

FedEx Location Information

Express Station ID: FEPA

Ground Terminal Id: WHLG

Sales Professional : Marie L. Cleveland

Phone Number : 847-420-9224

Field Engineer: Scott Gindt

Phone Number : 262-644-5749

Product Information

Commodity Code : 58	UN No :	Model Number: S-19765	Pcs. Per Pkg:
Values : 25.00	Product Description: 6 CHAMPAGNE BOTTLE SHIPPER -		

Packaging Information

Size : L(in): 16 **W (in):** 11 **H(in):** 15 **Wt (lb):** 24 **Outer Container Type:** Corrugated

Container Specs: B-Flute Singlewall 200 Burst Test

Other Outer Info: RSC

Inner Packaging I: Polystyrene **Inner Packaging II:** **Sealing Method:** PST
Foam mold

Other Inner Info: The wine bottles were packaged inside a polystyrene molded container within a corrugated shipping box.

Test Procedures Completed

Test Type : International - FedEx

Drop Height (in) : 30 inches **Drop Sequence :** Two Sets Free - Fall

Drop Results: No Visible Damage

Compression Factor: 5 **Compression Load (lbf) :** 573

Compression Results: Meets Minimum Specifications

Vibration Profile: International FedEx **Vibration Duration:** 90 Minutes Random

Vibration Results: No Visible Damage

Impact Sequence: **Impact Velocity (ft/s):**

Impact Results:

Other Applicable Tests: **Results:**

Test Results

Result: Passed 5/8/2014

Definitions of Results

- Passed:** A package, with article, that has passed all the Fedex Standard Testing Procedures. For commodities restricted under Liabilities Not Assumed in the Fedex Service Guide, Service Guide Terms and Conditions will take precedence.
- Failed:** A package, with article, that has failed all FedEx Standard Testing Procedures.
- Pending:** A package, with article, that has been tested to all FedEx Standard Test Procedures. Confirmation of results is subject to customer inspection.

Comments and Packaging Recommendations*

Note: Current Packaging
No visible damage noted after testing.

* Our provision of advice, assistance or guidance on the appropriate packaging of shipment does not constitute acceptance of liability, unless such advice, assistance or guidance is in writing from the FedEx Packaging Design and Development department and expressly accepts liability in the event of a damaged shipment.

Photos / Drawings (if Applicable)